



L21000 FENDER ## L4018DT-ID/L4018TK-ID  
L4018DT-ID/L4018TK-ID HOOD/BONNET

Update Date: 2026/03/03  
Printing Date: 2026/08/08



TC822-808-10

≡ Interchangeable      NI Not Interchangeable      >> New for Old      << Old for New

| No. | Part No.    | Part Name              | Qty | IC | Serial No./PIN | Remarks | Kg    |
|-----|-------------|------------------------|-----|----|----------------|---------|-------|
| 010 | TC822-47010 | FENDER(LH)             | 1   |    | <=143631       |         | 0.0   |
| 010 | TC822-47013 | FENDER(LH)             | 1   | >> | >=143632       |         | 0.0   |
| 020 | TC822-47000 | FENDER(RH)             | 1   |    | <=143631       |         | 0.0   |
| 020 | TC822-47003 | FENDER(RH)             | 1   | >> | >=143632       |         | 0.0   |
| 030 | 01754-50816 | BOLT,FLANGE            | 6   |    |                |         | 0.011 |
| 040 | TC402-61260 | GROMMET,25             | 2   |    |                |         | 0.0   |
| 050 | 30430-82670 | PLUG                   | 1   |    | <=136797       |         | 0.001 |
| 050 | 6C506-52742 | SEAL                   | 1   | NI | >=136798       |         | 0.0   |
| 060 | 01754-50816 | BOLT,FLANGE            | 14  |    |                |         | 0.011 |
| 070 | 02751-50080 | NUT,FLANGE             | 2   |    |                |         | 0.006 |
| 080 | TC404-29440 | GRIP,LH                | 1   |    |                |         | 0.0   |
| 090 | 02771-50100 | NUT,FLANGE             | 2   |    |                |         | 0.009 |
| 100 | TC822-29440 | SUPPORT(FENDER BRIDGE) | 1   |    |                |         | 0.0   |
| 110 | 01754-50820 | BOLT,FLANGE            | 2   |    |                |         | 0.015 |
| 120 | 01774-51020 | BOLT,FLANGE            | 2   |    |                |         | 0.02  |
| 130 | 01774-51016 | BOLT,FLANGE            | 3   |    |                |         | 0.02  |