


021500 GOVERNOR ADJUSTING BOLT [OLD] ## V3800DI-TE2-ZT/ZIN
S.No.<=2GBZ999 S.No.;<=2GBZ999
M9540DT ENGINE

Update Date: 2026/02/20
Printing Date: 2026/08/01



1G574-021-11

== Interchangeable NI Not Interchangeable >> New for Old << Old for New

No.	Part No.	Part Name	Qty	IC	Serial No./PIN	Remarks	Kg
010	1C010-54153	BOLT	1				0.005
015	1G031-54210	NUT(LOCK)	1				0.003
020	1C010-54120	BOLT,ADJUSTING	1				0.008
025	15841-92020	NUT	1				0.004
030	1C010-54120	BOLT,ADJUSTING	1				0.008
040	1G031-54210	NUT(LOCK)	1				0.003
050	15852-92330	NUT	2				0.005
060	15601-96650	PACKING	5				0.001
070	1G514-54100	ASSY BOLT,ADJUSTMENT	1		<=8ZZ999		0.01
070	1G570-54100	ASSY BOLT,ADJUSTMENT	1	NI	>=9A0001		0.01
070	1G570-54102	BOLT	1	>>	>=9L0001		0.008
090	15261-92020	NUT	1				0.004

= Interchangeable

NI Not Interchangeable

>> New for Old

<< Old for New

No.	Part No.	Part Name	Qty	IC	Serial No./PIN	Remarks	Kg
100	15021-33660	PACKING	1				0.001
110	15841-54220	NUT,CAP	1				0.006
120	16221-54420	CAP	1				0.001
130	----	PIPE,LOCK	2			NOT SALE	0.005
140	15841-54270	CAP	1				0.001
150	15852-92330	NUT	1				0.005
160	15601-96650	PACKING	1				0.001
170	15021-33660	PACKING	1				0.001