


021502 GOVERNOR ADJUSTING BOLT [NEW] ## V3800DI-TE2-ZT/ZIN
S.No.>=2GY0001 S.No.;>=2GY0001
M9540DT ENGINE

Update Date: 2026/02/20
Printing Date: 2026/08/01



1G574-021-14

== Interchangeable NI Not Interchangeable >> New for Old << Old for New

No.	Part No.	Part Name	Qty	IC	Serial No./PIN	Remarks	Kg
005	1G558-54350	BOLT,ASSY	1				0.007
010	1C010-54153	BOLT	1				0.005
015	1J094-54210	NUT(LOCK)	1				0.003
020	1C010-54120	BOLT,ADJUSTING	1				0.008
025	15841-92020	NUT	1				0.004
030	1G529-54350	BOLT,ASSY	1				0.011
035	1C010-54120	BOLT,ADJUSTING	1				0.008
040	1J094-54210	NUT(LOCK)	1				0.003
050	1J097-54380	NUT,CAP,ASSY	2				0.006
055	1J094-54280	CIRCLIP,INT	2				0.001
060	15601-96650	PACKING	3				0.001
070	1G570-54102	BOLT	1				0.008

= Interchangeable

NI Not Interchangeable

>> New for Old

<< Old for New

No.	Part No.	Part Name	Qty	IC	Serial No./PIN	Remarks	Kg
090	15261-92020	NUT	1				0.004
100	15021-33660	PACKING	1				0.001
110	15841-54220	NUT,CAP	1				0.006
120	16221-54420	CAP	1				0.001
130	----	PIPE(LOCK)	2			NOT SALE	0.01
140	15841-54270	CAP	1				0.001
150	15852-92330	NUT	1				0.005
160	15601-96650	PACKING	3				0.001
170	15021-33660	PACKING	1				0.001