


A01000 ACCELERATOR LEVER ## L4028
L4028 ENGINE

Update Date: 2026/03/03

Printing Date: 2026/08/08



= Interchangeable

NI Not Interchangeable

>> New for Old

<< Old for New

No.	Part No.	Part Name	Qty	IC	Serial No./PIN	Remarks	Kg
010	TC402-17127	LEVER,HAND ACCEL	1				0.41
030	TC422-10680	GRIP,ACCEL	1				0.0
040	30400-15210	NUT	1				0.005
050	TC822-44720	LEVER(ACCEL.ARM)	1				0.0
060	TD060-42870	PLATE,FRICTION	2				0.01
070	04015-50080	WASHER,PLAIN	1				0.01
080	TC832-10320	SPRING(ACCEL)	1				0.018
090	TC402-42840	WASHER	1				0.0
100	TC402-10270	CAP,SPRING	1				0.011
110	02156-50080	NUT	1				0.004
120	02751-50080	NUT,FLANGE	1				0.006
130	TC402-17322	LINK,ACCEL	1				0.12

This content is the information at the time of publication on this site, information such as the part name and part number may be different from the present. Illustrations of products and parts that are posted are image diagrams.

ca1580fb-47c9-4ade-b87d-ad777b9dd643

= Interchangeable **NI** Not Interchangeable **>>** New for Old **<<** Old for New

No.	Part No.	Part Name	Qty	IC	Serial No./PIN	Remarks	Kg
140	04013-50100	WASHER,PLAIN	1				0.004
150	05515-51000	PIN,SNAP	1				0.002
160	TC822-42900	ROD(ACCEL.)	1				0.0
170	TC402-42980	LINK,ACCEL ROD	1				0.02
180	02156-50080	NUT	2				0.004
190	04013-50080	WASHER,PLAIN	1				0.002
200	05511-50218	PIN,SPLIT	1				0.001
210	04013-50060	WASHER, PLAIN	1				0.001
220	05511-51615	PIN,SPLIT	1				0.001