


L21300 FENDER SUPPORT ## MX5000DT
MX5000DT HOOD/BONNET


Update Date: 2026/03/03
Printing Date: 2026/08/03

OLD


S. No. ; MX5000F : <=12074
MX5000DT : <=53854




S. No. ; MX5000F :
12075 to 15016
MX5000DT :
53855 to 58225



S. No. ; MX5000F :
15017 to 15321
MX5000DT :
58226 to 58974



TC059-818-10



TC059-034-12

== Interchangeable NI Not Interchangeable >> New for Old << Old for New

No.	Part No.	Part Name	Qty	IC	Serial No./PIN	Remarks	Kg
010	TC050-29213	SUPPORT,FENDER LH	1				0.001
020	TC050-29220	SUPPORT,FENDER RH	1		<=51215		4.0
020	TC050-29223	SUPPORT,FENDER RH	1	NI	>=51216		4.0
030	01774-51230	BOLT,FLANGE	4				0.043
040	01754-50820	BOLT,FLANGE	1		<=53296		0.015
040	01754-50825	BOLT,FLANGE	1	NI	>=53297		0.01
050	TC030-29232	SUPPORT,SEAT	1		<=53854		1.81
050	TC030-29233	SUPPORT,SEAT	1	>>	>=53855		1.81
050	TC030-29234	SUPPORT,SEAT	1	>>	>=58226		1.81
050	TC030-29235	SUPPORT,SEAT	1	NI	>=58975		1.81
060	01774-51020	BOLT,FLANGE	4				0.02
070	TC050-29244	STAY,FENDER	1				2.6
080	01754-50820	BOLT,FLANGE	2				0.015
090	01754-50816	BOLT,FLANGE	4				0.011
100	TC050-47212	COVER,FLOOR SHEET	1				1.95
110	01754-50816	BOLT,FLANGE	7				0.011